

2003 DODGE CARAVAN SE

Stock#: #36009708 | Sale Location: [Alaska](#) | Auction Time: 2024-12-27 18:30:00



Vehicle description

VIN:	1D4GP25313B***** (OK)
Document type:	Bill of Sale (Alaska)
Damage:	Collision
Primary damage:	Front End
Airbags:	Intact
Start Code:	Stationary
Keys:	Present
Actual Cash Value:	\$6,092
Estimated Repair Cost :	-

Vehicle details

Make:	DODGE
Model:	CARAVAN
Series:	SE
Body Style:	Passenger van
VIN:	1D4GP25313B*****
Mileage:	1 mi (Inoperable Digital Dash)

Bid Information

Current bid
\$0 USD
Buy It Now Price ?

Online Bidding Close:

12/27/2024 18:30 GMT

Sale Information

Document type:	Bill of Sale (Alaska) BOS-JUNK
DocuBrand:	
Sale Status:	Wait Certificate
Auction Time:	12/27/2024 18:30 GMT
Lane / Item	Lane: / Item: #0
Vehicle Location:	*****
Grid / Row:	/
Selling Branch:	AK - Anchorage
Seller:	*****
Data Last Updated:	01/16/2024 08:26 GMT

Vehicle Type:	Automobile
Vehicle Class:	Minivan
Engine Type:	3.3L V-6 180HP
Cylinders:	6 cylinder
Transmission:	Automatic
Fuel Type:	Flexible Fuel
Drivetrain:	Front Wheel Drive
Exterior Color:	Navy blue
Interior Color:	TAN
Restraint System:	Front Impact Airbag Passenger;front Impact Airbag Driver
Manufactured in:	United States

Equipment

Air Bags	1
Radio	PRESENT
Navigation	N/A
Rear Entertainment	N/A

2003 DODGE CARAVAN SE

Stock#: #36009708 | **Sale Location:** [Alaska](#) | **Auction Time:** 2024-12-27 18:30:00



WWW.USAAUTOLICIT.COM

Bid Information

Current bid

\$0 USD

Buy It Now Price ?

Online Bidding Close:

12/27/2024 18:30 GMT

Vehicle description

VIN:	1D4GP25313B***** (OK)
Document type:	Bill of Sale (Alaska)
Damage:	Collision
Primary damage:	Front End
Airbags:	Intact
Start Code:	Stationary
Keys:	Present
Actual Cash Value:	\$6,092
Estimated Repair Cost :	-

Vehicle details

Make:	DODGE
Model:	CARAVAN
Series:	SE
Body Style:	Passenger van
VIN:	1D4GP25313B*****
Mileage:	1 mi (Inoperable Digital Dash)
Vehicle Type:	Automobile
Vehicle Class:	Minivan
Engine Type:	3.3L V-6 180HP
Cylinders:	6 cylinder
Transmission:	Automatic
Fuel Type:	Flexible Fuel
Drivetrain:	Front Wheel Drive
Exterior Color:	Navy blue
Interior Color:	TAN

Sale Information

Document type:	Bill of Sale (Alaska) BOS-JUNK
DocuBrand:	
Sale Status:	Wait Certificate
Auction Time:	12/27/2024 18:30 GMT
Lane / Item	Lane: / Item: #0
Vehicle Location:	*****
Grid / Row:	/
Selling Branch:	AK - Anchorage
Seller:	*****
Data Last Updated:	01/16/2024 08:26 GMT

Restraint System:	Front Impact Airbag Passenger;front Impact Airbag Driver
-------------------	--

Manufactured in: United States

Equipment

Air Bags	1
Radio	PRESENT
Navigation	N/A
Rear Entertainment	N/A