

2013 KIA OPTIMA LX

Stock#: #39119370 | Sale Location: Illinois



Vehicle description

VIN:	5XXGM4A72DG*****
Document type:	SALVAGE CERTIFICATE (Illinois)
Primary damage:	Vandalized
Start Code:	Stationary
Keys:	Missing
Actual Cash Value:	\$8,447
Estimated Repair Cost :	\$9,830

Vehicle details

Make:	KIA
Model:	OPTIMA LX
Series:	-
Body Style:	-
VIN:	5XXGM4A72DG*****
Mileage:	0 mi
Vehicle Type:	AUTOMOBILE
Vehicle Class:	-

Bid Information

Bid status:	Not ready for sale
-------------	--------------------

Sale Information

Document type:	SALVAGE CERTIFICATE (Illinois)
DocuBrand:	
Sale Status:	Pure Sale
Auction Time:	Not ready for sale
Lane / Item	Lane: / Item: #0
Vehicle Location:	*****
Grid / Row:	/
Selling Branch:	IL - -
Seller:	*****
Data Last Updated:	03/01/2024 21:56 GMT

Engine Type:	2.4L 4
Cylinders:	4 cylinder
Transmission:	Automatic
Fuel Type:	Gasoline
Drivetrain:	Front Wheel Drive
Exterior Color:	Silver

2013 KIA OPTIMA LX

Stock#: #39119370 | **Sale Location:** Illinois



Vehicle description

VIN: 5XXGM4A72DG*****

Document type: SALVAGE CERTIFICATE (Illinois)

Primary damage: Vandalized

Start Code: Stationary

Keys: Missing

Actual Cash Value: \$8,447

Estimated Repair Cost : \$9,830

Vehicle details

Make: KIA

Bid Information

Bid status: Not ready for sale

Sale Information

Document type: SALVAGE CERTIFICATE (Illinois)

DocuBrand:

Sale Status: Pure Sale

Auction Time: Not ready for sale

Lane / Item Lane: / Item: #0

Vehicle Location: *****

Grid / Row: /

Selling Branch: IL - -

Seller: *****

Data Last Updated: 03/01/2024 21:56 GMT

Model:	OPTIMA LX
Series:	-
Body Style:	-
VIN:	5XXGM4A72DG*****
Mileage:	0 mi
Vehicle Type:	AUTOMOBILE
Vehicle Class:	-
Engine Type:	2.4L 4
Cylinders:	4 cylinder
Transmission:	Automatic
Fuel Type:	Gasoline
Drivetrain:	Front Wheel Drive
Exterior Color:	Silver